San Carlos Apache Tribe Department of Environmental Protection Brownfields Program Inventory Listing PUBLIC RECORD

Project Name - Status	Date of
Remarks	completion
1. Old EPA Building – Assessment and Demolishment completed	June 2017
Asbestos, based paint and hazardous materials found	
2. Old Security Building – Assessment & Demolishment completed	June 2017
Asbestos. Lead based paint and Hazardous Materials found	
3. Planning Department BuildingAssessment & Demo Completed	March 2019
Asbestos, mold, lead based paint found and building was abated and materials	
removed by Environmental Response Inc., Building was renovated and is used as	
class rooms for Apache College.	
4. Old Finance Building Assessment & abatement completed	April 2019
Asbestos, mold and lead based paint found and Environmental Response Inc.,	
abated by Environmental Response Inc., WIOA and Apache Language staff are	
utilizing the renovated building.	
5. Cutter Airport Building assessment and demolishment completed	August 2020
Asbestos and hazardous chemical found and Environmental Response completed	
the project. New Emergency Medical Service is pending a new building at this	
time.	
6. SCAT DEP (former EPA) building assessment completed	July 2019
Little asbestos found in back office within floor tile. Office not being utilized at	
this time.	
7. Bylas Police Sub-station assessment completed	June 2021
Little mold and asbestos found. Tribal Contraction Company are renovated the	
building at this time	
8. San Carlos Tribal Court and Police department/jail assessment &	October 2019
demolishment completed	
Building demolishment completed by Kary Environmental Service. Skate	
Park/Sports Complex is now in the entire area for younger generations.	
9. Old Head Start Building assessment and abatement completed	October 2019
Renovation of building is still in progress at this time.	
10. Peridot Head Start assessment completed by JRM Environmental	August 2022
Frame Caulking exterior doors and windows were found and roofing mastic on	
roofing area were also detected. Abatement will be scheduled in near future by	
Kary Environmental Services.	
11. San Carlos Boys & Girls Club building assessment completed	April 2022
Assessment was done by Kary Environmental Service in conjunction with Tribe's	
General Managers Office. Brownfields Coordinator overseen the inspection of the	
assessment. Assessment report pending copy for DEP office at this time. The	
building will be demolished by Kary Environmental Services was funding becomes	
available through General Managers Office.	
12. San Carlos Cattle Association assessment completed	April 2022

Updated 2/6/2024

	Updated 2/6/202	
Assessment completed by Kary Environmental Service. Funding pending to		
remove asbestos and lead based paint in 2023 fiscal year.		
13. San Carlos Café assessment completed	April 2022	
Assessment completed by Kary Environmental Service. Funding pending for		
abatement to be completed to remove asbestos and lead based paint in building.		
14. Seneca Lake Resort assessment completed	June 2022	
Assessment completed by Kary Environmental Service asbestos within the store		
area were found during sampling. Demolishment of entire resort is		
recommended pending funding from San Carlos Apache Tribe.		
15. San Carlos BIA Fire Department & San Carlos Public Library assessment	August 2022	
completed though BIA Facilities was responsible for the assessment.		
San Carlos Apache Tribe though BIA funding will demolish both facilities by Kary		
Environmental Services.		
16. Cutter Sawmill – Demolished	2023	
Demolished without assessment conducted.		
17. Point of Pines Cattle Ranch House – Assessment Completed	May 2023	
Some asbestos found in framing.		
18. Peridot Adult Living Center – Assessment completed	May 2023	
Some asbestos in tile.		
19. Nigosdzan Recycling Center – Haz. Cleanup	September 2023	
Non-RCRA Regulated Solid (Burnt E-Waste) 15 cubic yard boxes		
20. San Carlos Apache Market Garage	24	
21. Grace Lutheran Church	24	
22. Old Tribal Jail/KYAY Radio Station	24	
23. Tribal Diabetes Prevention Office		
24. U of A COOP Extension Office	24	
walk though assessment was completed and determine that asbestos and lead		
based paint is within the building pending environmental contractor conduct		
assessment. No funding available at this time.		
25. San Carlos Lake Store - UST Removed	August 2022	
Two Underground Storage Tanks were removed in August 2022 by Kary] ~	
Environmental Service no future development of new fuel system will be		
constructed.		
26. San Carlos Sanitation Yard - Haz Waste collection	24	
20. 20.1 30.133 50.1100.1 1010 1102 Proste concetton	<u> </u>	

Department of Environmental Protection's Brownfields Program (Tribal Response Program) will continue to update and work on brownfields inventory listings for the following facilities.